



Retroreflective Light Barrier RLR / ISN / ISD - 2/4/6-XC-OP

ISN-2/4/6XC-OP

Housing M30

ISD-2/4/6XC-OP ISD-2/4/6XC-OP **1258** 

II 3(2)G Ex nA [op is Gb] IIB T4 Gc

· Long range

• Type ISD, applicable in Ex Zones (0), 1, 2, (20), 21, 22

• Type ISN, applicable in Ex Zones (1),2, (21),22


Robust sensor for industrial applications

II 2(1)G Ex d [op is Ga] IIC T6 Gb

II 3(2)D Ex tc [op is Db] IIIA T13	5°C Dc IP67		1	I 2(1)D Ex	tb [op is Da] IIIB T100°C Db IP67	
Technical Data	Туре	RLR-2/4/6XC	ISN-2/4/6XC-OF		ISD-2/4/6XC-OP	
Type of Ex protection, Gas		NONE	II 3(2)G Ex nA [op is Gb] I	IB T4 Gc	II 2(1)G Ex d [op is Ga] IIC T6 Gb	
Type of Ex protection, Dust		NONE	II 3(2)D Ex tc [op is DI T135°C Dc IP67	b] IIIA	II 2(1)D Ex tb [op is Da] IIIB T100°C Db IP67	
Applicable in Ex Zones		None	Zones (1), 2, (21),	22	Zones (0), 1, 2, (20), 21, 22	
Range (adjustable)		IS./RLR- <b>2</b> XC(-OP) = 2m				
(on reflector D=83mm)		IS./RLR- <b>4</b> XC(-OP)=4m IS./RLR- <b>6</b> XC(-OP)=6m				
Response time		IS./RLR- <b>2/4</b> XC(-OP): 5ms, IS./RLR- <b>6</b> XC(-OP): 1ms				
Light source		visible red, 623nm				
Beam pattern (at a distance	e of 2m)			r.12°		
Maximum radiant intensity		NOTLIMITED	<=5mW/mm <sup>2</sup>		<=5mW/mm <sup>2</sup>	
Maximum radiant power		NOTLIMITED	< 35mW		< 15mW	
Supply voltage		24VDC +-10%				
Absolute maximum input voltage Um		30VDC				
Maximum current consumption		45mA 60mA				
Maximum power dissipation		1.6W				
Output, series RLR/ISN/ISD-2/4XC(-OP)		1 x PNP, short circuit protected, maximum 100mA				
Output, series RLR/ISN/ISD-6XC(-OP) and S181		1 x Push-Pull, short circuit protected, maximum 100mA				
Output impedance		appr.15Ω				
Pollution indication output VA		1 x PNP, short circuit protected, maximum 100mA				
Emitter disable input, only typesDI		PNP compatible, Ri=10kΩ				
Housing		M30, yellow brass, nickel plated, 6XC with additional optic				
Enclosure rating, at EN 60529		IP54	IP 54 IP67 IP67			
Shock and vibrating resistar	nce	Vibration: 30g over 20Hz to 2kHz. Shock:50g for each direction (X, Y, Z)				
Operating temperature range	e Tamb		-20°C < T <sub>amb</sub> < +60°C			
Connection cable			4 + PE x 0,5mm <sup>2</sup> , TPU, oil resistent, shielded, leads numbering marked, L=3m			
Connection cable, types xxx	⟨DI	6 + PE x 0,5mm <sup>2</sup> , PVC, shielded, leads numbering marked, L=3m				
Socket, types RLR/ISN-2/4/6XC S99		Socket M12, Lumberg type RSF 5, 5 terminals				
Accessories included, all types		- 2 nuts M30 (or 1 clamp, on request)				
Accessories included, only I	SN and ISD	- 1x Spare safety screw with packing ring for potentiometer sealing				
Accessories, included,		- 1x Safety lo	- 1x Safety lock device, mount at the cable connection,			
only ISN-2/4/6XC-OP S99		for locking the connection. (black synthetic device)				
			- 1x Warning plate "WARNING - Explosion Hazard - Do Not Dis-			
		connect While Circuit Is Live Unless Area Is Known To Be Non-				
		Hazardous", self-sealing, for gluing on the cable connector				
Accessories, not included		- Cord Set Lumberg RKTS 5-298/xx (straight type), or				
only RLR/ISN-2/4/6XC(-OP) S99		RKTW/RKWTH 5-298/xx (right angle type)				
Options		-Switching frequency: Up to 2kHz, on request				
		-Cable length: Up to 100m, on request				
		-ISD-2/4XC-OI	P <b>S43</b> : With a	additional	optic	
		-RLR-2/4XC <b>\$109</b> : Working temperature range -20°C to +100°C				
		-RLR/ISN/ISD-	-RLR/ISN/ISDXC(-OP) <b>\$147</b> : Special gluing of the lenses			
		-RLR/ISN/ISD-2/4XC(-OP) \$181: With push-pull output				
			-RLR/IS2/4/6XC(-OP)- <b>DI</b> : With emitter disable input (not for types S99)			
		-RLR/ISN/ISD-	6XC(-OP) <b>S218</b> : Low p	orofile len	ns for use with aeriation tube	
Function			- I A I	г		
Output and display			_ <del>&gt;</del>			
Output and display		Light b	eam interrupted 🏴		Light beam reflected $lacksquare$	
					by the triple mirror	
		LEI	D shows red	LE	D shows green or yellow	
Function at standard supp	ly voltage wiring:		• +24VDC		• +24VDC	
	Cable Socket	1 (1)	J .24VD0	, l	724VDC	
+24VDC	1 1	\ <u>'</u> +	PNP=OFF	Ţ	PNP=ON	
0V	2 3	b (1)	R 15Ω	Ŷ	R 15Ω	
Output	3 4				^√√√○ Out	
Pollution indicationoutput Disable input (onlyDI)	4 2 5 –	ما الد	NIDAL-ON	. 1	ALDAL OFF	
NC (to connect at 0V)	6 -	$\downarrow \qquad \downarrow \qquad$	NPN=ON (Only6XC	/	NPN=OFF (Only6xc	
PE	yel-grn 5	Y	and2/4XC S181)	Υ	and2/4XC S181)	
Cable shield	white -		→ 0V		→ • 0V	
Function at reversed supp	ly voltage wiring:		• +24VDC		• +24VDC	
	Cable Socket		V +24VDC	. 1	0 +24400	
+24VDC	2 3	$+$ $\uparrow$ $+$	PNP=ON		PNP=OFF	
0V	1 1	Y \(\frac{1}{2}\)	R 15Ω	P	R 15Ω	
Output	3 4		^\\\\ Out		^- Out	
Pollution indication output Disable input (onlyDI)	4 2 5 –	1 1	NDN-OFF	الم	NDN-ON	
NC (to connect at 0V)	6 -		NPN=OFF (Only6XC	β.	NPN=ON (Only6XC	
PE	yel-grn 5	Y	and2/4XC S181)	Υ	and2/4XC S181)	
Cable shield	white		• 0V			

Cable shield

white



## Mounting prescriptions Ex Protection:

It is necessary to take into consideration the valid international and national rules and regulations (EN 60079-14). The maximum input voltage Um=30VDC must not be exceeded. The local equipotential bonding have to be done. The protective earth (PE) is solid connected with the housing. The cable have to be installed and protected against damages. The cable with termination fittings, or in cable tray systems and installed in a manner to avoid tensile stress at the termination fittings. To connect cables inside hazardous locations only use certificated Ex e housings. All cable terminals must be connected outside hazardous locations. Additional optical lenses are not allowed in hazardous locations. In dust Ex zones, do not operate the sensors without fixed dustproof sealing crew. After adjust the potentiometer, the dustproof sealing crew with undamaged packing ring, must be screwed down. Damaged or lost screws or packing rings must be replaced.

Type ISD-.XC-OP: Applicable in Ex zones 1, 2, 21, 22. The limited optical

radiation can operate into hazardous locations 0 or 20.

Type ISN-.XC-OP: Only applicable in Ex zones 2, 22. radiation can operate into hazardous locations 1 or 21. The limited optical

Type ISN-.XC-OP S99: Only applicable in Ex zones 2, 22. The limited optical radiation can operate into hazardous locations 1 or 21. Do not separate the connector when the supply voltage is connected to the cable. When installing the sensor, the safety lock device must be fitted at the cable connector. The additional adhesive warning label must be fixed to the connector housing at the connection cable. Lumberg cordsets RKTS 5-298/xx (Straight type) or RKWTH 5-298/xx (Right angle type), are allowed ONLY. It necessary to take into consideration the mounting prescription of the connector manufacturer. In dusty locations, the protection cap for the sensor socket must be fitted, when no connection cable is connected.

mounting prescriptions:

Do not exceed the maximum ratings. The electrical connections must be exactly as shown in the connection diagram. The cable shield must be connected short. The cable shield should be connected to the protection earth, large-surfaced. Connection cables must not be installed parallel to high voltage cables

Do not exceed the maximum ratings.

Function

The sensor can only be driven with a Triplex mirror. Only 2 times broken light beams will be detected. The sensor works basically as light barrier on reflective mirrors. If the sensor detects reflected light, the output switches to +24VDC or 0V dependent of the polarity of the supply voltage. If the sensor works under safe conditions the LED shows green. If the sensor detects only poor reflected light, the LED shows yellow and the pollution indication output VA switches to +24VDC. If no reflected light will be recognized, the LED shows red, the outputs switches to 0V and the controloutput is switching OFF. The load on the output must be connected to 0V. Potentiometer adjustment

For the detection of thin, transparent films, it is necessary the potentiometer by the following procedure:

-Mount the sensor and the mirror.

- Turn the potentiometer left to the sensor is switching off.
- Turn the potentiometer right just to the sensor is switching on.

Check the safe function of the sensor. The output must works without any

the potentiometer a little more to the right side.

Sensors with disable input, types ...-..XC-DI (Not for types S99/109): If several sensors are installed close to another, it is necessary to use sensors with disable input. By using the disable input DI, each sensor can be controlled in a short reaction time. If only one sensor is activated in the same time, a mutual influence is precluded.

0V or not connected = emitter enabled High (24VDC) = emitter disabled

For a correct function the sensor must be enabled for at minimum >= 7.5ms (DI=0V). If the DI input will be disabled, the outputs holds the previous output

status from the last enabled time.
The DI input is PNP compatible.

## Maintenance

For a high reliability hold the lens and the mirror free from sediment. No special maintenance is required. If the lens or the mirror becomes dirty, they should be cleaned with a non-aggressive cleaning liquid. Equipment must only be repaired by the manufacturer. General safety instructions

Series ISN-XC-OP S99: "WARNING - EXPLOSION HAZARD - WHEN IN HAZARDOUS LOCATIONS, TURN OFF POWER BEFORE REPLACING OR WIRING MODULES. DO NOT DISCONNECT EQUIPMENT UNLESS POWER HAS BEEN SWITCHED OFF OR THE AREA IS KNOWN TO BE NONHAZARDOUS". The mounting of the sensor in dusty locations without fixed cordset or protection cap results in a high ignition risk. The sensors must not be used for Accident-Prevention! In worst case the output can change to any state! When installing and operating with the sensor, it is necessary to take into consideration the relevant international and other national regulations: EN 60079-14, ATEX 118a, single directive 1999/92/EC

The sensor and the fibre optic are conform to the following standards: EN IEC 60079-0:2018, EN 60079-1:2014, EN 60079-15:2010, EN 60079-28:2015, EN 60079-31:2014, EN 61000-4-2 to EN 61000-4-6, EN 61000-6-1/-2, EN 61000-6-4. ATEX directive: 2014/34/EU, Machine directive: 2006/ 42/EC, EMC directive: 2004/108/EC, RoHS directive: 2011/65/EU

General Notes, disposal We reserve the right to modify our equipment. Our equipment is designed such way, that it has the least possible adverse effect on the environment. It neither emit or contain any damaging or siliconized substances and use a minimum of energy and resources. No longer usable or irreparable units must be disposed of in accordance with local waste disposal regulations.

## EC-Declaration of conformity

Model ISD: EC-Certification No. BVS 10 ATEX E 130 X. DEKRA. Model ISN: ATEX declaration by manufacturer at 2014/34/EU. ATEX certification of quality type production of Ex devices at the directive 2014/34/EU, CE 1258, Eurofins. Certification No: SEV 21 ATEX 4580. The conformity of the devices with the EC standards and directives and the ECtype examination certificate and the observation of the Quality Safety System ISO 9001:2015 with the ATEX module "Production", declares:

Pablo Ledergerber, Matrix Elektronik AG

Elektronik AG (Manufacturer) Kirchweg 24 CH-5420 Ehrendingen info@matrix-elektronik.com ::+41 56 20400-20 <u>e</u>

**Tippkemper - Matrix GmbH** Meegener Str. 43 D-51491 Overath

Fax -19

info@tippkemper-matrix.com

:+49 2206 9566-0

<u>e</u>